



# Merancas Classroom Building

Merancas Campus

Weekly Update January 17, 2020



## Meetings & Milestones

### • **This Week:**

- Continue Insulating and Hanging Drywall on First Floor
- Continue Insulating and Hanging Drywall on Second Floor
- Continue Installing Window Frames
- Continue Underground HVAC 4-Pipe System
- Continue Second Floor Ductwork
- Continue Third Floor Ductwork
- Continue Second and Third Floor HVAC Piping Rough-In
- Continue Second and Third Floor Electrical Rough-In
- Continue Second Floor Plumbing and Mechanical Insulation
- Continue Third Floor Plumbing Rough-In
- Continue Plan South Masonry
- Begin Plan East Masonry

## Meetings & Milestones

### • **Next Week:**

- Continue Insulating and Hanging Drywall on First Floor
- Continue Insulating and Hanging Drywall on Second Floor
- Continue Installing Window Frames
- Continue Underground HVAC 4-Pipe System
- Continue Second Floor Ductwork
- Continue Third Floor Ductwork
- Continue Second and Third Floor HVAC Piping Rough-In
- Continue Second and Third Floor Electrical Rough-In
- Continue Second Floor Plumbing and Mechanical Insulation
- Continue Third Floor Plumbing Rough-In
- Begin Balance of Underground Electrical
- Continue Fire Protection Rough-In
- Continue Plan South Masonry

Progress Photos



**Continue First Floor  
Electrical Rough-In**



**Location: Electrical 169**



Progress Photos



**Place Monumental  
Stair Concrete**



**Location: Lobby 101**

Progress Photos



**Continue Telecom  
Room Sheathing and  
Electrical Rough-In**



**Location: MDF 109**

Progress Photos



**Continue Hanging  
Drywall**



**Location: Commons 142**



Progress Photos



**Continue Finishing  
First Floor Drywall**



**Location: DRE Lab 164**



Progress Photos



**Install Second Floor  
Electrical Panel  
Enclosures**



**Location: Electrical 234**

Progress Photos



**Continue Second  
Floor Wall Insulation**



**Location: Men 263**

Progress Photos



**Continue Hanging  
Second Floor  
Drywall**



**Location: MC Touchdown**

Progress Photos



**Begin Taping Second  
Floor Drywall**



**Location: Mechanical 233**



Progress Photos



**Begin Installing  
Third Floor VAVs**



**Location: Classroom 325**

Progress Photos




**Continue Third Floor  
Ductwork**



**Location: Classroom 309**

Progress Photos



**Continue Third Floor  
Overhead Plumbing**



**Location: Corridor 328**



Progress Photos



**Continue South  
Elevation Masonry**



**Location: South Elevation**



Progress Photos



**Begin East Elevation  
Masonry**




**Location: East Elevation**

Progress Photos



**Backfill 4-Pipe  
System**



**Location: Claytor West**



Progress Photos



**Continue Curtain  
Wall Framing**



**Location: South Elevation**

Conclusion of Weekly Update 01/17/2020

Our  
Passion<sup>®</sup>  
is Building<sup>®</sup>

