



Merancas Classroom Building

Merancas Campus

Weekly Update February 7, 2020



Meetings & Milestones

- **This Week:**

- Continue Taping and Finishing Drywall on First Floor
- Continue Priming First Floor Drywall
- Continue Second Floor Ductwork
- Continue Second Floor Plumbing and Mechanical Insulation
- Continue Insulating and Hanging Drywall on Second Floor
- Continue Second and Third Floor Electrical Rough-In
- Continue Third Floor Ductwork
- Continue Third Floor Plumbing Rough-In
- Continue Installing Curtain Wall System
- Continue Balance of Underground Electrical
- Continue Plan South Masonry
- Continue Plan West Masonry
- Continue Underground HVAC 4-Pipe System

Meetings & Milestones

• **Next Week:**

- Continue Taping and Finishing Drywall on First Floor
- Continue Priming First Floor Drywall
- Continue Second Floor Ductwork
- Continue Second Floor Plumbing and Mechanical Insulation
- Continue Insulating and Hanging Drywall on Second Floor
- Continue Second and Third Floor Electrical Rough-In
- Continue Third Floor Ductwork
- Continue Third Floor Plumbing Rough-In
- Continue Installing Curtain Wall System
- Continue Balance of Underground Electrical
- Continue Plan South Masonry
- Continue Plan West Masonry
- Continue Underground HVAC 4-Pipe System

Progress Photos



**Install Steel Floating
Bench Supports**



Location: Commons 102

Progress Photos



**Hang and Tape
Circulation Soffit**



Location: Circulation 120

Progress Photos



**Continue Insulating
Ductwork**



Location: Classroom 131

Progress Photos



**Continue Fire Alarm
Rough-In**



Location: Multi Purpose 119

Progress Photos



**Continue Insulating
Plumbing Piping**



Location: Janitor 209

Progress Photos



**Continue Finishing
Second Floor
Drywall**



Location: Gen Ed 268

Progress Photos



**Continue Overhead
Plumbing**




Location: Lab 322

Progress Photos



**Continue Third Floor
Electrical Rough-In**



Location: Classroom 335

Progress Photos




**Continue Third Floor
Ductwork**



Location: Chem Lab 314

Progress Photos



**Continue Third Floor
Plumbing Rough-In**



Location: Family 321

Progress Photos



**Install Hollow Metal
Doors at Mechanical
Rooms**



Location: Mech 208

Progress Photos



**Continue
Underground
Electrical**



Location: Plan South

Progress Photos



**Continue Installing
Curtain Wall Framing**



Location: Plan South

Progress Photos



**Continue South
Elevation Masonry**



Location: South Elevation

Progress Photos



**Continue West
Elevation Masonry**



Location: West Elevation

Progress Photos



**Continue Exterior
Masonry**



Location: North Elevation

Conclusion of Weekly Update 02/07/2020

Our
Passion
is Building®

