



# Merancas Classroom Building

Merancas Campus

Weekly Update February 21, 2020



## Meetings & Milestones

- **This Week:**

- Continue Sprinkler Pipe Rough-In
- Continue Taping and Finishing Drywall on First Floor
- Continue First and Second Floor Electrical Rough-In
- Continue Second Floor Ductwork
- Continue Insulating and Hanging Drywall on Second Floor
- Continue Third Floor Ductwork
- Continue Third Floor Plumbing Rough-In
- Continue Hanging Third Floor Drywall
- Set HVAC Fans in Mechanical Rooms
- Continue Installing Curtain Wall System
- Continue Plan South Masonry
- Continue Plan West Masonry
- Begin Plan North Masonry
- Continue Underground HVAC 4-Pipe System

## Meetings & Milestones

- **Next Week:**

- Continue Sprinkler Pipe Rough-In
- Continue Taping and Finishing Drywall on First Floor
- Continue First and Second Floor Electrical Rough-In
- Continue Second Floor Ductwork
- Continue Insulating and Hanging Drywall on Second Floor
- Begin Priming Second Floor Drywall
- Continue Third Floor Ductwork
- Continue Third Floor Plumbing Rough-In
- Continue Hanging Third Floor Drywall
- Set HVAC Fans in Mechanical Rooms
- Continue Installing Curtain Wall System
- Install Curtain Wall Glass
- Continue Plan South Masonry
- Continue Plan West Masonry
- Continue Plan North Masonry
- Continue Underground HVAC 4-Pipe System

Progress Photos



**Continue First Floor  
Electrical Rough-In**



**Location: Storage 113**

Progress Photos



**Continue Pulling  
First Floor Data  
Cables**



**Location: Corridor 154**

Progress Photos



**Continue First Floor  
Wall Insulation**



**Location: Commons 102**

Progress Photos



**Continue Second  
Floor Ductwork**



**Location: Classroom 229**

Progress Photos



**Set Mechanical  
Room Fans**



**Location: Mech 233**



Progress Photos



**Continue Third Floor  
Plumbing Rough-In**




**Location: Vestibule 318**

Progress Photos



**Continue Mechanical  
Room HVAC Piping**



**Location: Mech 342**

Progress Photos




**Continue Piping  
Third Floor VAVs**



**Location: Classroom 309**

Progress Photos



**Continue Installing  
Third Floor Blocking**




**Location: Science Lab 346**

Progress Photos



**Continue Hanging  
Third Floor Drywall**



**Location: Corridor 328**

Progress Photos



**Continue Finishing  
Third Floor Drywall**




**Location: Classroom 335**

Progress Photos



**Continue Installing  
Curtain Wall Framing**




**Location: North Elevation**

Progress Photos



**Continue North  
Elevation Masonry**



**Location: North Elevation**



Progress Photos



**Continue South  
Elevation Masonry**



**Location: South Elevation**

Progress Photos



**Continue West  
Elevation Masonry**



**Location: West Elevation**

Progress Photos



**Continue West  
Elevation Masonry**



**Location: West Elevation**

Conclusion of Weekly Update 02/21/2020

Our  
Passion<sup>®</sup>  
is Building<sup>®</sup>

