



# Merancas Classroom Building

Merancas Campus

Weekly Update March 13, 2020



## Meetings & Milestones

- **This Week:**

- Continue Sprinkler Pipe Rough-In
- Continue Taping and Finishing Drywall on First Floor
- Continue First and Second Floor Electrical Rough-In
- Continue Second Floor Ductwork
- Continue Taping and Finishing Drywall on Second Floor
- Continue Priming Second Floor Drywall
- Continue Third Floor Ductwork
- Continue Third Floor Plumbing Rough-In
- Continue Hanging Third Floor Drywall
- Continue Mechanical Room HVAC Piping
- Continue Installing Curtain Wall System
- Begin Installing Elevator
- Begin Installing South Elevation Sunshades
- Continue Plan East Masonry
- Continue Plan North Masonry

## Meetings & Milestones

- **Next Week:**

- Continue Sprinkler Pipe Rough-In
- Continue Taping and Finishing Drywall on First Floor
- Continue First and Second Floor Electrical Rough-In
- Continue Second Floor Ductwork
- Continue Taping and Finishing Drywall on Second Floor
- Continue Priming Second Floor Drywall
- Continue Third Floor Ductwork
- Continue Third Floor Plumbing Rough-In
- Continue Hanging Third Floor Drywall
- Continue Mechanical Room HVAC Piping
- Continue Installing Curtain Wall System
- Continue Installing Elevator
- Continue Installing South Elevation Sunshades
- Continue Plan East Masonry
- Continue Plan North Masonry

Progress Photos



**Begin Installing  
Elevator**



**Location: Commons 142**

Progress Photos



**Continue First Floor  
Data Cabling**



**Location: MDF 109**

Progress Photos



**Continue Electrical  
Room Wiring**



**Location: Electrical 169**

Progress Photos



**Continue Booster  
Pump Piping**



**Location: Sprinkler 167**

Progress Photos



**Continue AHU  
Mechanical Piping**



**Location: Mech 161**



Progress Photos



**Continue Mechanical  
Room Ductwork**




**Location: Mech 233**

Progress Photos



**Continue Acid Waste  
Piping**



**Location: Science Lab 346**

Progress Photos



**Continue First Floor  
Ceiling Grid**



**Location: Multi-Purpose 119**

Progress Photos



**Begin Installing First Floor Light Fixtures**



**Location: SGA Lounge 117**

Progress Photos



**Continue West  
Elevation Roof  
Masonry**



**Location: Area B Roof**

Progress Photos



**Complete Spray  
Foam**



**Location: Area A Roof**

Progress Photos



**Continue North  
Elevation Roof  
Masonry**



**Location: Area A Roof**

Progress Photos



**Begin Installing  
South Elevation  
Sunshade**



**Location: South Elevation**



Progress Photos



**Place Seed at 4-Pipe System**




**Location: West Claytor**

Progress Photos



**Begin Balance of  
Dumpster Enclosure  
Grading**



**Location: East Elevation**

Conclusion of Weekly Update 03/13/2020

Our  
Passion  
is Building®

