



Merancas Classroom Building

Merancas Campus

Weekly Update May 08, 2020



Meetings & Milestones

- **This Week:**

- Continue First, Second and Third Floor Electrical Rough-In
- Begin Installing Restroom Plumbing Fixtures
- Continue Second Floor Ceiling Grid
- Continue Second Floor Data Cabling
- Continue Second Floor Ductwork
- Continue Installing Interior Storefront Frames
- Continue Third Floor Ductwork
- Continue Masonry Joint Caulking
- Continue Campus Entrance Grading
- Continue Metal Panel Framing and Sheathing
- Install North Elevation Downspouts
- Install Knox Boxes
- Place Plan North Sidewalk
- Place Plan East Curb and Gutter
- Continue Site Grading

Meetings & Milestones

- **Next Week:**

- Continue First, Second and Third Floor Electrical Rough-In
- Continue Installing Restroom Plumbing Fixtures
- Continue Second Floor Ceiling Grid
- Continue Second Floor Data Cabling
- Continue Second Floor Ductwork
- Continue Installing Interior Storefront Frames
- Begin Installing Storefront Glass
- Continue Third Floor Ductwork
- Continue Masonry Joint Caulking
- Continue Campus Entrance Grading
- Continue Metal Panel Framing and Sheathing
- Continue Site Grading
- Place Plan South Sidewalks

Progress Photos



**Continue First Floor
Light Fixtures**



Location: DRE Lab 164

Progress Photos



Begin Installing Restroom Plumbing Fixtures



Location: Women 145

Progress Photos



**Begin Installing
Restroom Plumbing
Fixtures**



Location: Men 146

Progress Photos



**Continue Installing
Interior Storefront**



Location: STC Work 133

Progress Photos



**Begin High Ceiling
Electrical Rough-In**



Location: Library 122

Progress Photos



**Continue Second
Floor Ceiling Grid**



Location: Commons 212

Progress Photos



Install Knox Boxes



Location: West Elevation

Progress Photos



**Continue Installing
Canopy Plywood
Sheathing**



Location: West Elevation

Progress Photos



**Install Roof
Downspouts**



Location: North Elevation

Progress Photos



**Install East Elevation
Curtain Wall**



Location: East Elevation

Progress Photos



**Continue Plan South
Grading**



Location: Plan South

Progress Photos



**Prep Plan South
Sidewalks**



Location: Incidental

Progress Photos



**Place Plan East
Concrete Curb**



Location: Plan East

Progress Photos



**Place Plan North
Sidewalk**



Location: Plan North

Progress Photos



**Place Campus
Entrance Curb and
Gutter**



Location: Campus Entrance

Conclusion of Weekly Update 05/08/2020

Our
Passion[®]
is Building[®]

