



Merancas Classroom Building

Merancas Campus

Weekly Update May 15, 2020



Meetings & Milestones

• **This Week:**

- Continue First, Second and Third Floor Electrical Rough-In
- Install FRP Wall Finish
- Continue Installing Second Restroom Plumbing Fixtures
- Continue Second Floor Ceiling Grid
- Continue Second Floor Data Cabling
- Continue Second Floor Ductwork
- Begin Installing Second Floor Light Fixtures
- Continue Campus Entrance Grading
- Continue Metal Panel Framing and Sheathing
- Place Plan South Sidewalk
- Continue Site Grading

Meetings & Milestones

- **Next Week:**

- Continue First, Second and Third Floor Electrical Rough-In
- Continue Installing Second Restroom Plumbing Fixtures
- Continue Second Floor Ceiling Grid
- Continue Second Floor Data Cabling
- Continue Second Floor Ductwork
- Continue Installing Second Floor Light Fixtures
- Continue Metal Panel Framing and Sheathing
- Place Plan South Sidewalk
- Continue Site Grading

Progress Photos



**Install FRP Wall
Finish and Mop Sink**



Location: Housekeeping 160

Progress Photos



**Continue First Floor
Light Fixtures**



Location: Corridor 154

Progress Photos



**Install Stair 1 Cane
Rails**



Location: Stair 1

Progress Photos




**Continue Second
Floor Ceiling Grid**



Location: Conference 204

Progress Photos



**Begin Installing
Second Floor Light
Fixtures**



Location: Conference 251

Progress Photos



**Install Second Floor
Drinking Fountain**



Location: Corridor 237

Progress Photos



**Install Second Floor
Restroom Plumbing
Fixtures**




Location: Men 263

Progress Photos



**Continue Second
Floor Electrical
Rough-In**




Location: Electrical 234

Progress Photos



**Continue Third Floor
Electrical Room
Rough-In**




Location: Electrical 343

Progress Photos



**Continue Installing
Third Floor Home
Run Conduit**



Location: Vestibule 344

Progress Photos



**Hang Third Floor
Restroom Hard
Ceiling**



Location: Women 319

Progress Photos



**Continue Plan East
Site Grading**



Location: Plan East

Progress Photos



**Continue Metal Panel
Soffit Sheathing**



Location: North Elevation

Progress Photos



**Place Plan South
Concrete Sidewalk**



Location: Plan South

Progress Photos



**Place Plan South
Concrete Sidewalk**



Location: Plan South

Conclusion of Weekly Update 05/15/2020

Our
Passion[®]
is Building[®]

